

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2010 Levee Inspection Results

Reclamation District No. 2075 McMullin

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 2075 McMullin

Waterway			Bank	Unit Miles
Unit No. 01 San Joaquin River			Right	7.52
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/7/2010 - 4/7/2010			
DWR Inspector	Herman Phillips			
Accompanied By	Mr. Eddie Cordoza Reclamation District 2075			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2075 McMullin

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River							Right	7.52	04/07/2010 04/07/2010	Herman Phillips
LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.08	0.08	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	37.487987 ° -121.289663 °	37.487987 ° -121.289663 °	15 Y
2	1.11	1.16	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	37.738457 ° -121.281812 °	37.737835 ° -121.281708 °	1
3	1.19	1.20	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.737462 ° -121.281638 °	37.737322 ° -121.281563 °	3
4	1.26	1.44	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	37.736473 ° -121.281585 °	37.735173 ° -121.284033 °	4
5	1.32	1.32	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.735710 ° -121.282315 °	37.735710 ° -121.282315 °	5
6	1.41	1.41	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.735277 ° -121.283537 °	37.735277 ° -121.283537 °	6
7	2.32	2.32	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.731507 ° -121.293760 °	37.731507 ° -121.293760 °	7
8	4.54	4.54	Earthen Levee	Encroachments	LS	M	Agricultural Ditch	37.720852 ° -121.278078 °	37.720852 ° -121.278078 °	13
9	5.34	5.35	Supplemental	DWR Erosion Survey	WS	U	Inspector Comments: 2009: No major change; located in an oxbow; slope surface consist of very sandy material; exposed tree roots; recommend as a local maintenance issue, per CLRO CES Evaluation 2008 Report; Eddy Cordoza of RD 2075 is aware of the site; previously rated "U" [2009 SiteID:RD2075U1RM64.34]	37.727933 ° -121.274491 °	37.727933 ° -121.274491 °	2 Y
10	5.62	5.62	Earthen Levee	Trim / Thin Trees	WS	N	Tree stumps.	37.724947 ° -121.271103 °	37.724947 ° -121.271103 °	8
11	6.52	6.55	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	37.717362 ° -121.258437 °	37.719107 ° -121.258697 °	9
12	6.68	6.87	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	37.717362 ° -121.258437 °	37.714633 ° -121.258737 °	10
13	6.93	7.00	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	37.714010 ° -121.259605 °	37.713777 ° -121.260675 °	11
14	7.01	7.01	Earthen Levee	Trim / Thin Trees	WS	N	Tree stumps.	37.713815 ° -121.260743 °	37.713815 ° -121.260743 °	12

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.52	04/07/2010 04/07/2010	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.08
End Levee Mile	0.08
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Levee mile 0.08 standing on waterward side looking downstream of district, there is no grassed on the leve slope, the Maintaining Agency sprayed the slopes. The land side slope looks the same.

phillips_s_20100622_093.jpg



Levee Mile Report Line	1
Start Levee Mile	0.08
End Levee Mile	0.08
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Standing on landward side looking downstream from levee mile 0.08 levee slopes looking good.

phillips_s_20100622_094.jpg



Levee Mile Report Line	9
Start Levee Mile	5.34
End Levee Mile	5.35
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

2009: No major change; located in an oxbow; slope surface consist of very sandy material; exposed tree roots; recommend as a local maintenance issue, per CLRO CES Evaluation 2008 Report; Eddy Cordoza of RD 2075 is aware of the site; previously rated "U" [2009 SiteID:RD2075U1RM64.34]

SJR2009_RM64.34a.JPG



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2075 McMullin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	7.52	04/07/2010 04/07/2010	Herman Phillips

Levee Mile Report Line	9
Start Levee Mile	5.34
End Levee Mile	5.35
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
<p>2009: No major change; located in an oxbow; slope surface consist of very sandy material; exposed tree roots; recommend as a local maintenance issue, per CLRO CES Evaluation 2008 Report; Eddy Cordoza of RD 2075 is aware of the site; previously rated "U" [2009 SiteID:RD2075U1RM64.34]</p> <p>SJR2009_RM64.34f.JPG</p>	



Levee Mile Report Line	9
Start Levee Mile	5.34
End Levee Mile	5.35
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
<p>2009: No major change; located in an oxbow; slope surface consist of very sandy material; exposed tree roots; recommend as a local maintenance issue, per CLRO CES Evaluation 2008 Report; Eddy Cordoza of RD 2075 is aware of the site; previously rated "U" [2009 SiteID:RD2075U1RM64.34]</p> <p>SJR2009_RM64.34g.JPG</p>	



Levee Mile Report Line	9
Start Levee Mile	5.34
End Levee Mile	5.35
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
<p>2009: No major change; located in an oxbow; slope surface consist of very sandy material; exposed tree roots; recommend as a local maintenance issue, per CLRO CES Evaluation 2008 Report; Eddy Cordoza of RD 2075 is aware of the site; previously rated "U" [2009 SiteID:RD2075U1RM64.34]</p> <p>SJR2009_RM64.34d.JPG</p>	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor